Software Version: N/A

Firmware Version: V22.03.02

Recommended Use

This release is recommended for all affected products listed below. It is important to keep your diagnostic tool current for optimum performance and to take advantage of all added enhancements. Please reference your user's manual on performing a software/firmware update on your diagnostic scan tool or code reader.

Affected Product(s)

- (0x3AA)3030RSv1

New / Added Features & Functions

- Support vehicle up to 2022
- Added QR Code to get even more with the RepairSolutions2 mobile app.
  - Gain free access to:
    - Vehicle Health Reports
    - Verified Fixes and Parts Required
    - Predicted Repairs
- Added tool ID

Fixes / Updates

- Fix – VIN Decode: BMW, VW, Hyundai Kia
- Fix – ABS Read DTC: 2005 Subaru Subaru Legacy B4, 2.5L, 2019 Subaru Subaru Impreza B4, 2.0L, 1999 Honda Accord L4, 2.3L; SOHC; 16V
- Fix – ABS DTC Definition: 2006-2007 Nissan Xterra
- Fix – UI at Make selection
- Fix – Battery/ Alternator Test

Product Support

Please visit us at innova.com/support for additional information.

Copyright ©2022 IEC. All rights reserved